

Revision Date: 08.03.2023

BMW Group

Components

Regulation (EC) No. 648/2004, as amended

Windscreen washer without antifreeze

Product code : 83 12 4 B05 261, 83 12 4 B05 262

AQUA
SODIUM LAURETH SULFATE
DIPROPYLENE GLYCOL
PARFUM
SODIUM PYRITHIONE
Cyclohexanol, 2-(1,1-dimethylethyl)-, 1-acetate, (1R,2R)-rel-
Octanal, 2-(phenylmethylene)-, (2E)-
3-HEXENOL
ISOAMYL ACETATE
BENZISOTHIAZOLINONE
2-BROMO-2-NITROPROPANE-1,3-DIOL
BHT